



CARROT RIVER SCHOOL

July 2022

MONTHLY REPORT

Carrot River New School Replacement



Photo #01 – Pre-Construction, East Side of Gym, Basketball Tarmac, Playgrounds

Carrot River New School Replacement



Photo #02 – Pre-Construction, Existing School Entrance

Carrot River New School Replacement



Photo #03 – Pre-Construction, North Side of Gym, Field

Carrot River New School Replacement



Photo #04 – Pre-Construction, Existing West Trees to be Removed, Running Track

Carrot River New School Replacement



Photo #05 – Stripped Site

Carrot River New School Replacement



Photo #06 – Stripped Site

Carrot River New School Replacement



Photo #07 – Stripped Site



CARROT RIVER SCHOOL

August 2022

MONTHLY REPORT

Carrot River New School Replacement



Photo #01 – Piles along Grid Line 3

Carrot River New School Replacement



Photo #02 – Piles along Grid Line E looking from Grid Line 5 south

Carrot River New School Replacement



Photo #03 – Pile caps along Grid Line 2 looking from Grid Line E east

Carrot River New School Replacement



Photo #04 – Piles along Grid Line 2 at new main entrance to school

Carrot River New School Replacement



Photo #05 – West side of existing gym brick removed

Carrot River New School Replacement



Photo #06 – North east corner of existing gym brick removed with piles covered.

Photo #07 – Stripped Site



CARROT RIVER SCHOOL

September 2022

MONTHLY REPORT

Carrot River New School Replacement



Photo #01 – Elevator Pit

Carrot River New School Replacement



Photo #02 – Front Entrance looking south from Elevator

Carrot River New School Replacement



Photo #03 – Grade Beam along Grid Lines 8 & B looking south

Carrot River New School Replacement



Photo #04 – Piles along Grid Line 5 looking east

Carrot River New School Replacement



Photo #05 – Room 106 Masonry

Carrot River New School Replacement



Photo #06 – Room 106 Masonry



CARROT RIVER SCHOOL

October 2022

MONTHLY REPORT

Carrot River New School Replacement



Photo #01 – Clerestory Area

Carrot River New School Replacement



Photo #02 – Front Entrance

Carrot River New School Replacement



Photo #03 – Elevator Shaft

Carrot River New School Replacement



Photo #04 – Structural Steel southwest corner

Carrot River New School Replacement



Photo #05 – Room 106 Masonry

Carrot River New School Replacement



Photo #06 – Room 106 Masonry Steel

Carrot River New School Replacement



Photo #07 – Room 106 Masonry



CARROT RIVER SCHOOL

November 2022

MONTHLY REPORT

Carrot River New School Replacement



Photo #01 – General site view looking south

Carrot River New School Replacement



Photo #02 – Glulam installed

Carrot River New School Replacement




Photo #03 – Hoarding on Room 106 Masonry

Carrot River New School Replacement



Photo #04 – Rom 106 Masonry Acoustic Block

Carrot River New School Replacement



Photo #05 – Existing Gym Storage Demo

Carrot River New School Replacement



Photo #06 – Existing Gym Structural Scaffold



CARROT RIVER SCHOOL

December 2022

MONTHLY REPORT

Carrot River New School Replacement



Photo #1 – Gym bleachers being removed

Carrot River New School Replacement



Photo #2 – Gym looking north east

Carrot River New School Replacement



Photo #3 – Gym looking south west

Carrot River New School Replacement



Photo #4 – Gym west wall hoarding

Carrot River New School Replacement



Photo #5 – Existing gym storage room

Carrot River New School Replacement



Photo #6 – Existing gym storage

Carrot River New School Replacement



Photo #7 – PAA room looking north

Carrot River New School Replacement



Photo #8 – Room 106 east masonry wall hoarding

Carrot River New School Replacement



Photo #9 – Room 106 west wall with sound block

Carrot River New School Replacement



Photo #10 – North exterior

Carrot River New School Replacement



Photo #11 – North exterior



CARROT RIVER SCHOOL

January 2023

MONTHLY REPORT

Carrot River New School Replacement



Photo #1 – Room 106 Trusses and Roof Decking

Carrot River New School Replacement



Photo #2 – Roof Parapets over Administration offices

Carrot River New School Replacement



Photo #3 – Site looking at Grade 3 and Elementary Art Classrooms

Carrot River New School Replacement



Photo #4 – Hoarding on North West corner

Carrot River New School Replacement



Photo #5 – Stairwell 4 in North West Corner

Carrot River New School Replacement



Photo #6 – Phase 1 Undergrounds for Slab Prep

Carrot River New School Replacement



Photo #7 – Exterior Brick Veneer

Carrot River New School Replacement



Photo #8 – Clerestory Protection and Roof Deck



CARROT RIVER SCHOOL

May 2023

MONTHLY REPORT

Carrot River New School Replacement



Photo #1 – Exterior Brick on Phase 4

Carrot River New School Replacement



Photo #2 – Exterior EIFS Vapour Barrier

Carrot River New School Replacement



Photo #3 – Front Entrance

Carrot River New School Replacement



Photo #4 – Student Commons Bench Area

Carrot River New School Replacement



Photo #6 – Mechanical on Main Floor

Carrot River New School Replacement



Photo #7 – Second Floor Washroom Block Fill

Carrot River New School Replacement



Photo #8 – Second Floor Classroom Drywall

Carrot River New School Replacement



Photo #9 – Second Floor Classroom Exterior Wall Insulation



CARROT RIVER SCHOOL

June 2023

MONTHLY REPORT

Carrot River New School Replacement



Photo #1 – EIFS on Phase 3

Carrot River New School Replacement



Photo #2 –EIFS on Phase 3

Carrot River New School Replacement



Photo #3 – EIFS Vapour Barrier on Phase 4

Carrot River New School Replacement



Photo #4 – Mono Glass on Overhang Phase 1

Carrot River New School Replacement



Photo #5 – Elevator Installed

Carrot River New School Replacement



Photo #6 – Resource Center

Carrot River New School Replacement



Photo #7 – Second Floor Drywall and Insulation

Carrot River New School Replacement



Photo #8 – PAA Overhead Door



Photo #9 – Fire Sprinkler System



Photo #10 – Classroom Mudded Walls



Photo #11 – Student Commons Feature Stair



CARROT RIVER SCHOOL

September 2023

MONTHLY REPORT

Carrot River New School Replacement



Photo #1 – Landscaping

Carrot River New School Replacement



Photo #2 – Landscaping

Carrot River New School Replacement



Photo #3 – Bus Lane



Photo #4 – EIFS Wood Grain

Carrot River New School Replacement



Photo #5 – Student Commons



Photo #6 – First Floor Phase 4 Classroom Drywall

Carrot River New School Replacement



Photo #7 – Room 106



Photo #8 – Corridor 201.2 Flex Rooms Area

Carrot River New School Replacement



Photo #9 – Wood Doors



Photo #10 – Science Lab

Carrot River New School Replacement



Photo #11 – Mech Room



CARROT RIVER SCHOOL

October 2023

MONTHLY REPORT

Carrot River New School Replacement



Photo #1 – Site Works



Photo #2 – Dust Collector

Carrot River New School Replacement



Photo #3 – Student Commons




Photo #4 – Millwork with countertop Sink

Carrot River New School Replacement



Photo #5 – Second Floor Washroom Area



Photo #6 – Resource Center Millwork

Carrot River New School Replacement



Photo #7 – Resource Room TFL Panels



Photo #8 – Science Lab Millwork

Carrot River New School Replacement



Photo #9 – Main Floor Washroom



Photo #10 – Entrance by PAA



CARROT RIVER SCHOOL

December 2023

MONTHLY REPORT



Photo #1 – School Signage



Photo #2 – Meeting Room



Photo #3 – Reception Desk



Photo #4 – Main Floor Display Cases



Photo #5 – Home Economics Room



Photo #6 – First Floor Washroom Entrance




Photo #7 – Change Room



Photo #8 – Stairs



Photo #9 – Second Floor Washroom Entrance



Photo #10 – Second Floor Breakout Rooms



Photo #11 – Resource Centre